


November 16, 2011

ADDENDUM NO. 2

**DOCTORS HEALTHCARE AND
REHABILITATION CENTER**



BYSP PROJECT NO. 10106

TO: Arthur Construction Co.

Item No. 9:

Specification 08210: At Note 5. Materials: Remove note c. Interior Wood Doors: 1 3/4" thick 6 panel hardboard door by Jeld-Win or approved equal.

Item No. 1:

Sheet A101, A102: At SPECIFIED ITEMS alter the following ITEM 21: Mirror B shall be Contractor Furnished/Contractor Installed.

Item No. 2:

Sheet A101, A102: Clarification for SPECIFIED ITEM 22: This Mirror corresponds with MR-3 on the MATERIALS LEGENDS Sheet ID002. This mirror shall be unframed.

Item No. 6:

Sheet A101, A102: Clarification: In COORIDORS A104, A112, A116, B123, B129, 200, 232 install chair rail (TEMPLATE SERVICES, INC. TS-CH 29) or approved equal. Chair rail shall be red oak. Stain and finish to match handrail. The chair rails shall cover the transition between two separate wall finishes. Chair rails are to be installed at the same height as the handrails. Chair rails shall be installed at **ALL** spaces between handrails and **ALL** other locations where handrails are not indicated to cover the finish transition between the two wall finishes.

Item No. 7:

Sheet A406: Add Crash Rail detail to 15/A406 as shown on attached sheet A406.3. Crash rail to be part of Deductive Alternate 2.

Item No. 8:

Sheet A407: At Details 2 and 4: Change sound batt insulation to 6" in lieu of 3 1/2" as shown.

Item No. 3:

Sheet ID002: Clarification for MR-3 (Mirror): Reference this mirror to SALON in lieu of PUBLIC RESTROOMS.

Item No. 4:

Sheet ID002: Add the following appliances to the MATERIALS LEGEND: HOOD-1, WASH-1, & DRY-1 as shown on the attached sheet.


Item No. 5:

Sheet ID003: At B114 KITCHEN, add HOOD-1 under the Misc. Column.


End of Addendum

Addendum 2 11/16/11
Sheet ID002 – MATERIALS LEGEND

HOOD-1	Range Hood	Whirlpool	UXT4Q30AYS	30" Non-Ventiled Range Hood	Stainless	Install Per Manufacturers Recommendations.	Contractor or Owner May Purchase from Aptura. Please see contact information above to get pricing.
WASH-1	Washer	Whirlpool	WTW4850XQ	Energy Star Washer	White	Install Per Manufacturers Recommendations.	Contractor or Owner May Purchase from Aptura. Please see contact information above to get pricing.
DRY-1	Dryer	Whirlpool	WED5500XW	Electric Dryer	White	Install Per Manufacturers Recommendations.	Contractor or Owner May Purchase from Aptura. Please see contact information above to get pricing.



NOVEMBER 16, 2011



NOTE: HANDRAILS SHALL SUPPORT A VERTICAL LOAD OF 250 LBS. ENDS SHALL BE MITERED AND RETURNED TO WALL AT ALL LOCATIONS

<p>⊕ BASE BID HANDRAIL HRL-1 AND CRASH RAIL CR-1 AS SHOWN IN THE MATERIALS LEGEND (INTERIORS)</p>
--

DEDUCT. ALT. 2 15 HAND RAIL/CRASH RAIL

SCALE : 3/4" = 1'-0"

ADDENDUM 2

COPYRIGHT 2011 BUNDY, YOUNG, SIMS & POTTER, Inc.



BUNDY, YOUNG, SIMS & POTTER, INC.
 ARCHITECTS/PLANNERS/INTERIOR DESIGN

1005 Ninth St. - Suite 200
 Wichita Falls, TX 76301
 Tel. (940)761-2404
 Fax (940)761-2119

Dick Bundy, AIA Tom Young, AIA(1949-1993) Rick Sims, AIA David Potter, AIA

RENOVATIONS & ALTERATIONS FOR: JOB NO. 10106

DOCTORS HEALTHCARE DATE 11/16/11

AND REHABILITATION DRAWING NO. A406.3

9009 WHITE ROCK TRAIL DALLAS, TEXAS